


Sensor Sensitivity Solution



Sensor in Bracket




Sensor Remove from Bracket



Sensor Back Line



Sensor Back Remove with Screwdriver



**Turn Dial with Small
Screwdriver**

**Clockwise = less sensitive
Counter-Clockwise = more
sensitive**

Sensor Fix. Turn Clockwise in this orientation to make the sensor less sensitive.

We suggest a 180 degree turn and then test if it works.

The sensor **should not** be triggered when the bottle and drawer are closed and the bottle is **empty**.

It **should** trigger when the bottle and drawer are closed and the bottle is **full**.